Work Order ID 54444



Page 1

December 9, 2009 11:29:37 AM

Item ID:

D4013-041

Accept



Setup Start



Revision ID:

Wearplate Assembly Item Name:

Required Date: 16/12/2009

Start Date:

09/12/2009

Start Qty: 10.00

Req'd Qty: 10.00



Cust Item ID:

Customer:

Start Run

Reference:

Approvals:

Process Plan:

Tooling:

Date:

SPC (Y/N):

Date:

Date:

Stop

Sequence ID/ Work Center ID Operation Description

Revision Nbr

Set Up/ Run Hours Draw Number Draw Rev.

Plan Accept Qty Code

Reject Qty

Reject Insp. Stamp Number

Draw Nbr

С

D4013 100

QC:

Waterjet FLOW CNC Waterjet Memo

1-Cut as per Dwg D4013-1

Dwg Rev: Prog Rev:

2-Deburr if necessary

0.00

0.00

B 9-12-10

110

QC

Quality Control

QC2- Inspect parts off machine FAI/FAIB

Memo

0.00

0.00

12 9-17-10

Dail Ae	OSpace	LIU							, 1	
W/O:				WORK ORDER CHANGES						
DATE	STEP		PR	OCEDURE CHANGE	В	/ Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
		1								
					•					
Part No	:		PAR #:	Fault Category:	NCR:	es No D	QA:	Date:		
	R	esolution:		Disposition:	QA: N/	C Closed: _		Date: _		

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B		Verification	Approval	Approval QC Inspector			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng				
	ļ					· ·					
,											
1											

December 9, 2009 11:29:37 AM

Item ID:

D4013-041

Accept



Setup Start

Stop



Revision ID:

Item Name:

Wearplate Assembly

Start Date:

09/12/2009

Start Qty: 10.00

Req'd Qty: 10.00



Cust Item ID:

Customer:

Reference:

Approvals:

Required Date: 16/12/2009

Process Plan: _____ Date: ____

Date:

Tooling:

Date:

Start Run



SPC (Y/N):

Date:_

Stop

Sequence ID/ Work Center ID

120

Quality Control

Operation Description

QC:

QC8- Inspect parts - second check

Memo

Set Up/ **Run Hours** **Draw** Number

Draw Rev.

Plan Qty Code

Reject Accept Qty

Reject Insp. Number Stamp

130



Brake NC

Bend as per dwg

Memo

Memo

0.00

0.00

0.00

8009/12/17

0

140



Quality Control

OC5- Inspect part completeness to step on W/O

2) Sorlializ

Duit Aci	Ospace	· LCC							,		
W/O:		AND THE RESERVE OF THE PARTY OF	WORK ORDER CHANGES								
DATE	STEP	PRO	CEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
								l			
								_			
Part No	•		Fault Category: NCR			NCR: Yes No DQA: Dat					
Resolution:		esolution:	Disposition	n:	_ QA: N/C CI	osed:		Date: _			
NCR:		1	WORK ORD	ER NON-CONFORMA	NCE (NCR	1)					
DATE	STEP	Description of NC	Corrective Action		Section B		cation	Approval	Approval		
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti	ion C	Chief Eng	QC Inspector		
									<u> </u>		
		,									
						i I					
				*							
					:						

	•	 	_				
_		 L	Λ	2000	11.20.	27	1 1 1

December 9, 2009 11:29:37 AM

Requi: ca Date: 16/12/2009

Item ID:

D4013-041

Revision ID:

Wearplate Assembly Item Name:

Start Date:

09/12/2009

Start Qty: 10.00

Req'd Qty: 10.00



Accept

Setup Start

Stop

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: _____ Date: ____

Tooling: SPC (Y/N): Date:

Date:

Run



Stop

Reject

Sequence ID/ Work Center ID

Operation Description Set Up/ **Run Hours** Draw Number Draw Rev.

Plan Code Accept Qty

Reject Qty

PL 10-1-28

Insp. Number

Stamp

150

Large Fab

Large Fab

Memo

QC: _____ Date: ___

0.00

0.00

1- Weld cup, stud as per dwg use DT9550 A/R S.S. ROD BATCH: M 108/60

2- Apply hardfacing on wearplate and on studs (studs only 5 places not the cups) as indicated on dwg

A/R HARDCOAT 2059B BATCH: M 1/35+/

160

Quality Control

QC5- Inspect part completeness to step on W/O

=> 8 (aloch >9

OC9- Inspect visual per QSI004- Fusion Welds

0.00

170

QC

Memo

Memo

0.00

G/10/01/29

Quality Control

Dart Aeı	ospace	e Ltd							• , •	
W/O:			WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE				Date	te Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
		, . .		The state of the s						
		·		•						
				<u> </u>		·				
Part No: PAR #: Resolution:										
		Dispositio	n:	QA: N/C CI	QA: N/C Closed:					
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCF	R)				
DATE	OTED	Description of NC	Corrective Action Section			Verifi	cation	Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date		ion C	Chief Eng	QC Inspector	
	:									
· · · · · · · · · · · · · · · · · · ·							·· ··			

Work Order II	D 54444
---------------	---------



Page 4

December 9, 2009 11:29:37 AM

Required Date: 12/2009

Item ID:

D4013-041

Accept



Setup Start



Revision ID: Item Name: **Start Date:**

09/12/2009

Wear, late Assembly

Start Qty: 10.00

Req'd Qty: 10.00

Cust Item ID:

Customer:

Reference:

Process Plan: _____ Date: ____

Tooling:

Date:

Draw

Rev.

Run

Reject

Qty

Start

Approvals:

Date:

SPC (Y/N):

Set Up/

Run Hours

Date:

Stop

Number Stamp

Insp.

Sequence ID/ **Work Center ID**

180

Powdercoat

Powder Coating

Operation Description

Black Sandtex(Ref:4.3.5.7) per QSI005 4.3

M10564Z

START: 8:15AM 0.00

Temp: 320°F

Draw

Number

***MASK THREADS AND HEXAGONAL OPENING PRIOR TO FIN: 8:45 pu (0-02-0) HI

Plan

Code

Accept

Qty

Reject

190

Memo

QC3- Inspect Part Finish

0.00

0.00

BR 10-02.01

Quality Control

200

Packaging

Packaging

Identify as per dwg & Stock Location: 266

0.00

Memo

0.00



Dart /	4eros _i	pace l	Ltd
--------	--------------------	--------	-----

									•	
	WORK ORDER CHANGES									
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
									1	
		PAR #:	Fault Categ	ory:	NCR: Ye	R: Yes No DQA: Date:				
Resolution:			Disposition	l:	QA: N/C	Closed: _		Date: _		
NCR:		\	WORK ORDE	R NON-CONFORM	ANCE (NO	CR)				
DATE	STED	Description of NC	Corrective Action Section B			Verificatio			Approval	
DAIL	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng	cription Sign & Date		N& Section C		QC Inspector	
						-		ļ		
,										
						:				

NOTE: Date & initial all entries

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

Picklist Print

December 9, 2009 11:29:41 AM

Work Order ID: 54444

D4013-041

Wearplate Assembly Parent Item Name:

Comments:

M304S16GA

Parent Item:

IPP RevA: New issue 09.10.26 DD verified by:JLM

Purchased

RevB prelim per ECN 99.698p 09.11.02 DD verified

by:EC

redesign 09.11.12 DD verified by:EC

IPP RevB:

IPP RevC:

IPP RevD: revC as per

No

sf

400.6457 10.2105

Start Date: 09/12/2009

Start Qty: 10.00

189-12-10

Required Date: 16/12/2009

Required Qty: 10.00

304/316 Sheet .063

Warehouse	<u>Loc</u>	<u>Oty</u>	Loc Code		
Location					
Main Warehouse					
MAT	400.645	56737			
106860	1	6.018			
111924	25.168	39737			<u></u>
112442	29	.8899			
112567	0	.2973		,	
112885	9	.2715		•	
113295		320			113 295
	150	Each	66.0000	30.0000	

D4013-3

Manufactured

Q 10-1-25

Stud

	·		
5	4675	X	30
	, 0 , 5		

Warehouse	Loc Qty	Loc Code	
Location			
Main Warehouse			
ST139	40		
53940	40		
Main Warehouse			
WA	26		
53183	20		
53827	6	•	

		,								
W/O:			WO	RK ORDER CHANC	GES					î Ç
DATE	STEP	PR	OCEDURE CHAN	IGE	E	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
•										
·.										
Part No		PAR #:								
	Resolution:								Date: _	
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCR)			
DATE	CTED	Description of NC			Section B Veri			cation Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		ign & Date	Section C		Chief Eng	QC Inspector
· · · · · · · · · · · · · · · · · · ·				·						
										T V V V V V V V V V V V V V V V V V V V
 										

Picklist Print

December 9, 2009 11:29:41 AM

Work Order ID: 54444

Parent Item:

D4013-041

Parent Item Name:

Wearplate Assembly

Comments:

IPP RevA: New issue 09.10.26 DD verified by:JLM

RevB prelim per ECN09-698p 09.11.02 DD verified

by:EC

redesign 09.11.12 DD verified by:EC

IPP RevB:

IPP RevC:

IPP RevD: revC as per

D4013-5

No Manufactured.

150

Each

98.0000 60.0000

Start Date: 09/12/2009

Start Qty: 10.00

E 10-1-25

Required Date: 16/12/2009

Required Qty: 10.00

Page 2

Cup

D4013-9

B	54676	x60

Manufactured No

Loc Code Loc Qty Warehouse Location Main Warehouse 98 WA 12 53828 53941

86 150 Each

35.0000 20.0000



El- 10-1-25



B54677 x 20

Warehouse	Loc Qty	Loc Code
Location		
Main Warehouse		
ST	35	
53829	5	
53948	30	

Duit Ac	oopaoc	Ltu								
W/O:			W	ORK ORDER CHANG	ES					-
DATE	STEP	PRO	CEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	į									
	}									ii
Part No	:	PAR #:	Fault Cate	gory:	_ NCR	: Yes N	o DQ .	A :	_ Date: _	
	R	esolution:	Dispositio	n:	QA:	N/C Clos	sed:		Date: _	
NCR:		\	WORK ORD	ER NON-CONFORM	ANCE	(NCR)				
DATE	STEP	Description of NC			tion B	0:	Verific	cation	Approval	Approval
	3121	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector
					ļ					

Picklist Print

December 9, 2009 11:29:41 AM

Page 3

Work Order ID: 54444

Parent Item:

D4013-041

Parent Item Name:

Wearplate Assembly

Comments:

IPP RevA: New issue 09.10.26 DD verified by:JLM

RevB prelim per ECN09-698p 09.11.02 DD verified

by:EC

redesign 09.11.12 DD verified by:EC

Start Date: 09/12/2009

Required Date: 16/12/2009

Start Qty: 10.00

Required Qty: 10.00

IPP RevC:

IPP RevD: revC as per

IPP RevB:

150

D4013-11

Manufactured No

Each

34.0000 20.0000



EL 10-1-25

B54679 x 20

Warehouse	Loc Qty	Loc Code	
Location			
Main Warehouse			
ST	30		
53954	30		
Main Warehouse			
WA	4		
53830	4		

Dail Ac	ospace	LU							•
W/O:			W	ORK ORDER CHANG	ES	***************************************			,
DATE STEP		PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							:		
Part No	:	PAR #:	Fault Cate	egory:	_ NCR: Yes	No DQ	A:	Date: _	
	Re	esolution:	Dispositi	on:	_ QA: N/C CI	osed:		Date: _	
NCR:			WORK ORE	DER NON-CONFORMA	ANCE (NCF	R)			
		Description of NC		Corrective Action Sect	ion B	Verifi	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date		ion C	Chief Eng	QC Inspector
	•							4	

24444


DART AEROSPACE LTD	Work Order:	STEEN STEEN
DART ALKOOF AGE 213	•	
Description: WEAR OLATE	Part Number:	D40B
Inspection Dwg:74/3-1 Rev: C		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

	X	First Article	·[Prototype
--	---	---------------	----	-----------

Drawing Dimension		Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø	050	+ 005-001	753	<u> </u>			
Ø	635	130 800. +	,676	/	₽ ** .		IMPOSEDING TO GET
\overline{A}	1.88	100 - 610 +	T SEA	*	188		impossible to GET GET TOOL RADIUS TO
72	370	4 010	.757	¥			HOLES THAT WATE
	1.750	4 00	1,751	X-	ļ•		
	1.50	4- 030	1,504	k	<u> </u>		
	761.6	4_ 00	2.124	×	<u> </u>		
	2.75	4 ,30	2.750	6			
	760,	4-00	.674	No			
	2,438	4 010	2.936	×			
	6.876	4 .00	6.879	y			
	7.371	4 00	7771	×			
	12.146	4- 00	12.146	34		·	
·	14.458	1 2 2 2	IW.458	%			N
	18.458	7- 00	18.458	r		·	
	73,95%	T.,	73,958				
	10.26 10.26	4-02	25.04	17			
	, 063	7- :010	1054	3-	•		
	,063	17-31386					
<u></u>	<u></u>						Sec.
			1 .	1			
	<u> </u>	+	+	1	1		


Measu	red by:	iB	Audited by:	3	Prototype Approv	al:	N/A
		9-11-75	Date:	09/12/11	Da	te:	N/A
	5-4	I Observe	-	/ / / /	Revise	i by	Approved
Rev	Date	Change New Issue		0 D4013/	04/ KJ/JLM		





ıı	rEM	QTY -041	P/N	DESCRIPTION			
	1	X	D4013-041	WEARPLATE ASSEMBLY			
-	3	1	D4013-1	WEARPLATE			
\vdash	4	3	D4013-3	STUD			
T	5	6	D4013-5	CUP			
-	6	2	D4013-9	STUD			
	7	2	D4013-11	STUD			
-	21	Δ/R	20598	HARDCOAT			

SHOP COPY RETURN TO ENGINEERING UNCONTROLLED COPY SUBJECT TO AMENDMENT WITHOUT NOTICE WORK ORDER NO. 31444

С	SIMPLIF REDESI LONGER	Y DESI GNED I R USED	GN FOR TEM 5;); CHAN	R MANUFACTURING PURPOSES; ELIMINATED D4013-7 CUP (NO IGED FINISH FROM GREY TO	мв	09.11.11	
B	REDESI				МВ	09.11.02	
- A	NEW IS:				мв	09.10.22	
REV.			7	DESCRIPTION	BY	DATE	
DESIGN B				DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA			
CHECK	ED	1	15 N	DRAWING NO. D4013		REV. C	
APPROVED DE APPR.		1	9	WEARPLATE ASSEM	BLY	SCALE NTS	
DATE 09.11.11				COPYRIGHT © 2009 BY DART THE COOMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNIC WRITTEN PERMISSION PROM OWN TA	O ON THE EXPRE	SI TI TAHT HOSTIONCO SE	







Ø0.266 Ø0.625^{+0.000} THRU R0.100 TYP 0.507 TYP - 0.233 -- 0.466

D4013-5 CUP

0.031 X 45° CHAMFER - 0.200 -0.563

SECTION C-C D6-5

DESIGN DART AEROSPACE LTD DRAWN HAWKESBURY, ONTARIO, CANADA DRAWING NO. CHECKED REV. C D4013 MFG. APPR. SHEET 5 OF 5 TITLE APPROVED WEARPLATE ASSEMBLY DE APPR.

COPYRIGHT 6 2009 BY DART AEROSPACE LTD

NS OCCUMENT B PRIANT AND CONFIDENTIAL AND IS SUPPLED OF THE LIMETES CONFITTION THAT IT IS

NOT TO BE USED FOR ANY NAMEDIC AND CONSUMEDATED TO ANY OTHER PRIAD WITHOUT
WAITTHE PRIMASSION PRIOR BAT PARIOPHOLE VIET.

DATE

09.11.11

REF. DART SPEC. M304R
2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: NONE
7) WEIGHT: 0.03 lbs EACH

8

NOTES: 1) MATERIAL: AISI 304/316 STAINLESS STEEL ROUND BAR PER ASTM A276 REF. DART SPEC. M304R

3

SCALE

D